Oil Field Environmental Incident Summary

Responsible Party: MARATHON OIL COMPANY **Well Operator:** MARATHON OIL COMPANY

Well Name: WENINGER USA 44-34H

Field Name: REUNION BAY Well File #: 19064

Date Incident:9/2/2016Time Incident:14:30Facility ID Number:County:MOUNTRAILTwp:152Rng:93Sec:34Qtr:

Location Description:

Submitted By: Callie Karrigan Received By:

Contact Person: Keith Mingus

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
29.5 Gallons 29.5 Gallons 29.47 gallons

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/16/2016 Clean Up Concluded: 9/3/2016

Risk Evaluation:Explosive atmosphere

Areal Extent:

2 ft x 5 ft off the north side of location

Potential Environmental Impacts:

The release was controlled quickly due to the Operator being on location; however, there was a slight mist that went off the edge of location. Slight potential impact to vegetation.

Action Taken or Planned:

Well was shut-in for repairs on the flare and treater. This incident will be investigated internally with corrective actions. All affected soil will be removed for disposal and replaced with new soil and scoria.

Wastes Disposal Location: Secure Energy

Agencies Involved: MHA, TAT Environmental, NDIC

Updates

Date: 9/6/2016 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred within the MHA Nation's boundaries.